


**OPEL Astra: 1DWY170**

Vinnnumber:	<b>W0LPC6DA9DG010100</b>	Versionname:	<b>ASTRA BER ecoFLEX Essentia S&amp;S 95PK</b>
First Registrationdate:	<b>21/09/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>136826</b>	Power Kw:	<b>70</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1525</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Luggage cover
Windows electric F	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

215/60/16/99 V Steel				
Summer tyres:	Fr.L.	<b>Semperit: 4 mm</b>	Fr.R.	<b>Semperit: 4 mm</b>
	Re.L.	<b>Semperit: 4 mm</b>	Re.R.	<b>Semperit: 4 mm</b>

**Assistance equipment**

Spare tyre compact	<b>Yes</b>	Jack	<b>Yes</b>
--------------------	------------	------	------------

Total cost ex VAT	<b>520,00</b>
Front bumper, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Door F R, Bump(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Door R R, Bump(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Wing R R, Scratch(es), LI - Repair and paint (complete)	<b>308,20</b>



Door R L, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>

