



MERCEDES CLA: 1GAL910			
Vinnumber:	WDD1173011N060077	Versionname:	CLA BER 200 CDI 136PK
First Registrationdate:	6/12/2013	Fiscalpower:	
Expertise Mileage:	118455	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3423
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather and alcantara
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Summer tyres:	225/45/17/91 W LightMetal			
	Fr.L.	Dunlop: 7 mm	Fr.R.	Dunlop: 7 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	875,60
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	-------------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Dirty, Cleaning 72,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80

