


BMW 1: 1GHF535

Vinnnumber:	WBA1C91030J521171	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	7/02/2014	Fiscalpower:	
Expertise Mileage:	154253	Power Kw:	85
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1223
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

205/55/16/91 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	811,56
-------------------	--------

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display


Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---------------------------------------------------------------------	--------



Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

No pictures to display

Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	220,18
---------------------------------------------------------------------	--------



Wing F R, Chemical polution, LI - Repair and paint (complete) 220,18



Roof, Bump(s), PDR - Knock out without painting 63,00

