



AUDI A1: 1HAU139			
Vinnnumber:	WAUZZZ8X2EB119843	Versionname:	A1 SB Attraction 5-tr.90PK Aut.
First Registrationdate:	5/06/2014	Fiscalpower:	
Expertise Mileage:	111357	Power Kw:	66
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2505
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	205/55/15/88 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1160,04
Door frame F R, Scratch(es), It - Spot repair			115,56



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	294,56
---	---------------





Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rocker panel inner R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)	254,68
---	--------



Window F R door, Scratch(es), E - Replace	148,00
---	--------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Wing R R, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Interior, Dirty, Acceptable	0,00
-----------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44
---	--------



Bonnet, Bump(s), PDR - Knock out without painting	82,80
---	-------

