


AUDI A3: 1EIN680

Vinnumber:	WAUZZZ8P9DA060388	Versionname:	A3 SB TDie
First Registrationdate:	14/12/2012		Attract.Start/Stop DPF
Expertise Mileage:	95588	Fiscalpower:	105PK
Bodytype:	Hatchback	Power Kw:	77
Gearbox:	MAN 5 VIT	Body color	Brown
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Battery functioning	Yes	Oil level	OK
Number of doors	5	Parking lot	1115
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	VS		
Oil level	OK		
Registration Certificate Car (BE)	No		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/65/15/91 MS LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment





Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1029,09
Wing R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Stain, Cleaning	9,60



Door R R, Bump(s), LI - Repair and paint (complete)	366,35
---	---------------



Mirror side blinker R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), It - Spot repair	115,56
	
Seat cover R L, Stain, Cleaning	9,60
	
Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	268,18
	
Roof, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	259,80
	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	