



AUDI A7 SPORTBACK: 1NJP508

Vinnumber:	WAUZZZ4G3GN143219	Versionname:	3.0 TDI 160KW QUATTRO S TRONIC DCT 4WD
First Registrationdate:	4/03/2016	Fiscalpower:	
Expertise Mileage:	25443	Power Kw:	160
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3515
Maintenance:	SERVICE IN 4800KM 212D		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	
Type of headlighting:	Headlighting Xenon
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	235/55/17/103 H LightMetal			
Summer tyres:	Fr.L.	Fulda: 7 mm	Fr.R.	Fulda: 7 mm
	Re.L.	Fulda: 7 mm	Re.R.	Fulda: 7 mm
	235/55/17/103 H LightMetal			
Winter tyres:	Fr.L.	Fulda: 8 mm	Fr.R.	Fulda: 8 mm
	Re.L.	Fulda: 8 mm	Re.R.	Fulda: 8 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	779,92
--------------------------	---------------

Bumper Trim F, Missing, E - Replace	69,60
--	--------------



Interior, Dirty, Cleaning	12,00
----------------------------------	--------------



Bumper R, Scratch(es), LI - Repair and paint (complete) 349,16



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

