


BMW X1: HG7614

Vinnumber:	WBAVN71020VX11908	Versionname:	X1 sDrive18d 143PK
First Registrationdate:	5/06/2014	Fiscalpower:	
Expertise Mileage:	135229	Power Kw:	105
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3733
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Xenon
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/50/17/94 H Steel			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	0,00
-------------------	-------------

Wheel covers (all), Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	-------------

No pictures to display

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	-------------



Door R L, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display