


**BMW 316: 1FTL070**

Vinnumber:	<b>WBA3D91010J412780</b>	Versionname:	<b>3 BER 316d 116PK</b>
First Registrationdate:	<b>18/10/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>131744</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4512</b>
Maintenance:	<b>PLUS 1900 KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
GPS storage	Rear parking sensors
GPS storage	<b>HD</b>
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/60/16/92 H LightMetal</b>			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	306,80
-------------------	--------

Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Maintenance, Maintenance, P - Check	0,00
-------------------------------------	------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Seat cover F L, Worn, P - Check 0,00



Wing R R, Bump(s), Acceptable 0,00

*No pictures to display*

Wing R L, Bump(s), Acceptable 0,00

*No pictures to display*

Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Front bumper, Bad repair, LI - Repair and paint (complete) 211,80



Door F R, Bump(s), Acceptable 0,00

*No pictures to display*

Door F L, Bump(s), Acceptable 0,00

*No pictures to display*

Tailgate, No damage, P - Check 0,00



Alloy rim F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Roof, Scratch(es), Acceptable 0,00

*No pictures to display*