



FORD GALAXY: 1KBA270

Vinnumber:	WF0MXXGBWMEA17305	Versionname:	1.6 TDCI 85KW ECONETIC S/S TREND STYLE
First Registrationdate:	23/03/2015	Fiscalpower:	
Expertise Mileage:	182728	Power Kw:	85
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4315
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/60/16/99 H LightMetal			
Summer tyres:	Fr.L.	Semperit: 3 mm	Fr.R.	Semperit: 3 mm
	Re.L.	Semperit: 6 mm	Re.R.	Semperit: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 2410,00

Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Floor covering F L, Hole, Smart repair



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Bump(s), Acceptable 0,00

No pictures to display

Grill frame, Damaged, E - Replace 108,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 369,84



Roof pillar R, Bump(s), PDR - Knock out without painting 63,00



Bumper R, Bump(s), Smart repair 110,64



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Wing R L, Scratch(es), LI - Repair and paint (complete) 369,84



Interior, Dirty, Cleaning 72,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02

