



| BMW X5: 1KUZ445 | | | |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnumber: | WBAK5410500H69473 | Versionname: | 3.0 XDRIVE30D 4WD AUTO |
| First Registrationdate: | 9/07/2015 | Fiscalpower: | |
| Expertise Mileage: | 77569 | Power Kw: | 190 |
| Bodytype: | SUV | Body color: | White |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3405 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| Options | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| GPS storage | HD Luggage cover |
| GPS storage | Rear parking sensors |
| Windows electric F | |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Seats F heated | |
| Type of headlighting | Headlighting Xenon |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |


| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

| Degree of wear | | | | |
|----------------|-----------------------------------|--------------------------|-------|--------------------------|
| Summer tyres: | 315/35/20/110 W LightMetal | | | |
| | Fr.L. | Bridgestone: 3 mm | Fr.R. | Bridgestone: 3 mm |
| | Re.L. | Bridgestone: 3 mm | Re.R. | Bridgestone: 3 mm |

| Assistance equipment | |
|---|------------|
| Runflat | Yes |
| Total cost ex VAT | 0,00 |
| Alloy rim R L polished, Bad repair, Forfeit | 0,00 |



| | |
|---|------|
| Alloy rim F L polished, Scratch(es), Acceptable | 0,00 |
| No pictures to display | |
| Front bumper, Scratch(es), Acceptable | 0,00 |
| No pictures to display | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| No pictures to display | |
| Alloy rim R R polished, Bad repair, Forfeit | 0,00 |



Alloy rim F R polished, Scratch(es), Acceptable 0,00

No pictures to display