



## CITROEN C4 Picasso: 743BCZ

Vinnumber:	<b>VF7UA9HZC9J306848</b>	Versionname:	<b>GR.C4 PICASSO 7pl Business FAP 110PK</b>
First Registrationdate:	<b>2/12/2009</b>	Fiscalpower:	
Expertise Mileage:	<b>96094</b>	Power Kw:	<b>80</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Red</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2410</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

## Options

Radio CD	Luggage cover
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

## Degree of wear

	<b>215/55/16/93 H Steel</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 6 mm</b>	Fr.R.	<b>Goodyear: 6 mm</b>
	Re.L.	<b>Uniroyal: 6 mm</b>	Re.R.	<b>Uniroyal: 6 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	488,35
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F L, Scratch(es), E - Replace	30,00



Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen trim, Bump(s) and scratch(es), It - Spot repair	110,00



Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), E - Replace	30,00



Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), LI - Repair and paint (complete)	318,35

