




LEXUS RX450: 319BEK			
Vinnumber:	<b>JTJBC11A002015211</b>	Versionname:	<b>RX 450h Privil?ge Pack 249PK Aut.</b>
First Registrationdate:	<b>2/01/2010</b>	Fiscalpower:	
Expertise Mileage:	<b>183817</b>	Power Kw:	<b>183</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4309</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Seats F L ventilated
GPS storage	Seats F R ventilated
GPS storage	<b>HD</b> Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
Winter tyres:	<b>235/55/19/105 MS LightMetal</b>			
	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

Assistance equipment			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>776,04</b>
Bumper R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Seat cover F L, Damaged, Acceptable			<b>0,00</b>



Door F R, Scratch(es), LI - Repair and paint (complete)	<b>382,02</b>
---	---------------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

*No pictures to display*

Door R R, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Dashboard, Glue residues, Forfeit	12,00
-----------------------------------	-------

