



HYUNDAI i30: 1ESM056			
Vinnnumber:	TMAD381UAEJ027057	Versionname:	i30 CROSSWAGON Lounge 110PK
First Registrationdate:	8/03/2013	Fiscalpower:	
Expertise Mileage:	147463	Power Kw:	81
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3125
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Summer tyres:	205/55/16/91 V LightMetal			
	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Hankook: 3 mm	Re.R.	Hankook: 3 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes

Total cost ex VAT	886,25
Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35

	Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Bonnet, Bump(s), Acceptable	0,00
<i>No pictures to display</i>		
	Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Roof, Chemical pollution, LI - Repair and paint (complete)	481,50



Interior, Dirty, Cleaning 72,00



Rear wiper blade, Damaged, E - Replace 14,40



Windscreen, Stone chip(s), Acceptable 0,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display