



## CITROEN C4 Picasso: 1FGP278

|                         |                          |              |                               |
|-------------------------|--------------------------|--------------|-------------------------------|
| Vinnnumber:             | <b>VF7UARHB8DJ686059</b> | Versionname: | <b>GR.C4 PICASSO</b>          |
| First Registrationdate: | <b>24/06/2013</b>        |              | <b>7pl.Excl.FAP BMP 150PK</b> |
| Expertise Mileage:      | <b>137209</b>            | Fiscalpower: | <b>Aut</b>                    |
| Bodytype:               | <b>MPV</b>               | Power Kw:    | <b>110</b>                    |
| Gearbox:                | <b>Automatic</b>         | Body color   | <b>Blue</b>                   |
| Transmission:           | <b>Front</b>             | Paint type   | <b>Metalic</b>                |
| Fueltype:               | <b>Diesel</b>            | Rims summer  | <b>Aluminium</b>              |
| Battery functioning     | <b>Yes</b>               | Oil level    | <b>OK</b>                     |
| Number of doors         | <b>5</b>                 | Parking lot  | <b>1228</b>                   |
| Number of seats         | <b>7</b>                 |              |                               |
| Number head rests       | <b>7</b>                 |              |                               |
| Rims summer             | <b>Aluminium</b>         |              |                               |
| Category                | <b>Passenger Car</b>     |              |                               |
| Oil level               | <b>OK</b>                |              |                               |

## Options

|                                |                              |                       |                          |
|--------------------------------|------------------------------|-----------------------|--------------------------|
| Radio CD                       |                              | Central consol F      |                          |
| GPS storage                    | <b>HD</b>                    | Luggage cover         |                          |
| GPS storage                    |                              | Front parking sensors |                          |
| Windows electric F             |                              | Rear parking sensors  |                          |
| Windows electric R             |                              | Type of Tow bar       | <b>Tow bar removable</b> |
| Steering wheel multifunctional |                              |                       |                          |
| Radio multimedia               |                              |                       |                          |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                       |                          |
| Type of Lining                 | <b>Lining fabrics</b>        |                       |                          |
| Type of climate control        | <b>Autom climate control</b> |                       |                          |

## Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position       | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission        | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake           | <b>OK</b> |                     |            |

## Degree of wear

| 215/55/16/93 V LightMetal |       |                       |       |                       |
|---------------------------|-------|-----------------------|-------|-----------------------|
| Summer tyres:             | Fr.L. | <b>Uniroyal: 6 mm</b> | Fr.R. | <b>Uniroyal: 6 mm</b> |
|                           | Re.L. | <b>Uniroyal: 6 mm</b> | Re.R. | <b>Uniroyal: 6 mm</b> |

## Assistance equipment

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

Total cost ex VAT 306,56

Sill outer L, Bump(s) and scratch(es), It - Spot repair 211,56



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), Acceptable

0,00

*No pictures to display*