



**RENAULT Scenic: 1EJR636**

Vinnnumber:	<b>VF1JZ140648238358</b>	Versionname:	<b>SCENIC Energ.Dynamique 110PK</b>
First Registrationdate:	<b>1/01/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>139355</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Light Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4108</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Luggage cover	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	<b>Tow bar fixed</b>
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather and alcantara</b>	
Type of climate control	<b>Autom climate control</b>	
Sport seats		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/60/16/92 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Dunlop: 5 mm</b>	Fr.R.	<b>Dunlop: 5 mm</b>
	Re.L.	<b>Dunlop: 5 mm</b>	Re.R.	<b>Dunlop: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

<b>Total cost ex VAT</b>	<b>1804,58</b>
--------------------------	----------------

<b>Rocker panel inner R L, Bump(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>115,56</b>
--	---------------



<b>Bumper R, Damaged, Smart repair</b>	<b>110,64</b>
--	---------------



<b>Door R L, Scratch(es), LI - Repair and paint (complete)</b>	<b>318,35</b>
--	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Interior, Dirty, Cleaning 24,00



Bonnet, Bump(s), Acceptable 0,00

*No pictures to display*

Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Unclapsed, N - Fit/Remove 96,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68

