



SAAB 9-3 cabrio: 1DTM330

Vinnnumber:	Y53FF79S846013449	Versionname:	
First Registrationdate:	30/03/2004	Fiscalpower:	
Expertise Mileage:	169812	Power Kw:	129
Bodytype:	Cabriolet	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2732
Number of doors:	2		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining leather
Type of climate control:	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Toyo: 8 mm	Fr.R.	Toyo: 8 mm
	Re.L.	Toyo: 8 mm	Re.R.	Toyo: 8 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	424,56
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Windscreen, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Worn, Acceptable	0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), It - Spot repair 115,56



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Bump(s), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 24,00

