



VOLKSWAGEN Caddy: 1ERK716			
Vinnnumber:	<b>WV2ZZZ2KZDX097524</b>	Versionname:	<b>CADDY MAXI LIFE 2PLC Dark&amp;Cool DSG 102PK</b>
First Registrationdate:	<b>1/03/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>142315</b>	Power Kw:	<b>75</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3806</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Central consol F
Windows electric F	Rear parking sensors
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
	<b>205/55/16/94 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 4 mm</b>	Fr.R.	<b>Goodyear: 4 mm</b>
	Re.L.	<b>Goodyear: 4 mm</b>	Re.R.	<b>Goodyear: 4 mm</b>

Assistance equipment		
Spare wheel	<b>Yes</b>	Jack <b>Yes</b>
Total cost ex VAT	<b>1030,69</b>	
Bonnet, Chemical polution, LI - Repair and paint (complete)	<b>217,56</b>	



Seat cover R L, Stain, Cleaning	<b>12,00</b>
---------------------------------	--------------



Front bumper, Scratch(es), Acceptable	<b>0,00</b>
---------------------------------------	-------------

<i>No pictures to display</i>	
Roof, Chemical polution, LI - Repair and paint (complete)	<b>361,13</b>



Wing F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wing R L, Chemical polution, LI - Repair and paint (complete)	231,15
---	--------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	158,85
---	--------



Luggage space cover, Missing, E - Replace	50,00
---	-------

