



RENAULT MEGANE GRANDTOUR: 1FMP16Z			
Vinnnumber:	VF1KZ140650242781	Versionname:	1.5 ENERGY DCI 110 TOMTOM? EDITION
First Registrationdate:	12/02/2014	Fiscalpower:	
Expertise Mileage:	133728	Power Kw:	81
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2202
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
GPS storage	SD Luggage cover
GPS storage	Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear			
Summer tyres:	205/55/16/91 H LightMetal		
	Fr.L.	Fr.R.	
	Continental: 4 mm	Continental: 4 mm	
	Re.L.	Re.R.	
	Continental: 4 mm	Continental: 4 mm	

Assistance equipment	
Spare wheel	Yes Jack Yes
Total cost ex VAT	544,50
Maintenance book, Missing, Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Bump(s), PDR - Knock out without painting	63,00

	Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Rear window, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		

<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Stain, Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Chemical pollution, LI - Repair and paint (complete)	481,50

