



**VOLKSWAGEN Sharan: YN8435**

Vinnnumber:	<b>WVWZZZ7NZEVO16375</b>	Versionname:	<b>SHARAN Sunshine BMT</b>
First Registrationdate:	<b>4/12/2013</b>	Fiscalpower:	<b>St/St 140PK</b>
Expertise Mileage:	<b>168427</b>	Power Kw:	<b>103</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4731</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Sun Roof electric
GPS storage	Panoramic roof
GPS storage	HD Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>215/60/16/95 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 0 mm</b>	Fr.R.	<b>Continental: 0 mm</b>
	Re.L.	<b>Continental: 0 mm</b>	Re.R.	<b>Continental: 0 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>618,96</b>
Headlight R, Damaged, Acceptable			<b>0,00</b>



**Interior, Stain, Cleaning** 24,00





Alloy rim R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Rear window, Scratch(es), E - Replace 420,00




Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper R, Scratch(es), Smart repair 110,64



Ceiling, Burned, Smart repair 64,32



Alloy rim R R, Scratch(es), Acceptable 0,00

*No pictures to display*