



VOLKSWAGEN Passat: 1FNC386			
Vinnnumber:	<b>WVWZZZ3CZEE022224</b>	Versionname:	<b>PASSAT VAR Comfortline 136PK</b>
First Registrationdate:	<b>26/08/2013</b>	Fiscalpower:	<b>136PK</b>
Expertise Mileage:	<b>91442</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Break</b>	Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2104</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
	<b>215/55/16/97 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Pirelli: 6 mm</b>	Re.R.	<b>Pirelli: 6 mm</b>

Assistance equipment			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>

Total cost ex VAT	<b>1632,50</b>
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>308,20</b>



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>
---	---------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper grille, Damaged, E - Replace 74,00



Bonnet, Bump(s), Acceptable 0,00

No pictures to display