



VOLVO V40: 1FL1840			
Vinnnumber:	YV1MV8481E2091879	Versionname:	V40 D2 Base 115PK
First Registrationdate:	6/08/2013	Fiscalpower:	
Expertise Mileage:	49751	Power Kw:	84
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	BINN 18153KM	Parking lot:	4306
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment			
Repair kit	No	Compressor	Yes
Total cost ex VAT			488,44
Alloy rim R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing R L, Bump(s), PDR - Knock out without painting			82,80



Bonnet, Scratch(es), LI - Repair and paint (complete)	290,08
---	---------------



Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F L, Scratch(es), It - Spot repair	115,56

