



VOLKSWAGEN Golf: 1GAL908			
Vinnumber:	WVWZZZAUZEW188253	Versionname:	GOLF BER Highline 105PK
First Registrationdate:	6/12/2013	Fiscalpower:	
Expertise Mileage:	75423	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1531
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Adaptive cruise control	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Winter tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment	
Spare tyre compact	Yes Jack Yes
Total cost ex VAT	318,35
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), LI - Repair and paint (complete)	318,35

	Wing R R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display