







1207

# SKODA Octavia: NA4206

Vinnumber: TMBJJ9NE1F0110784 First Registrationdate: 25/11/2014 Expertise Mileage: 175332 Bodytype: Gearbox: MAN 6 VIT Transmission: Front Fueltype: Diesel Battery functioning Yes Number of doors 5 Number of seats 5 Number head rests 5 Rims summer Aluminium Category Passenger Car Oil level ок

Versionname: OCTAVIA COMBI Elegance Fiscalpower: Power Kw: 110 Body color White Paint type Metalic Rims summer Aluminium Oil level OK

Parking lot

#### Options

Radio CD Sun Roof electric GPS storage HD Central consol F GPS storage Luggage cover Windows electric F Front parking sensors Windows electric R Rear parking sensors Cruise Control

Steering wheel multifunctional

Registration Certificate Car (BE)

Seats F heated Radio multimedia

Type of headlighting Headlighting Xenon Type of GPS GPS big screen color Type of Lining Type of climate Autom climate control

Lining fabrics

Yes

## **Limited Technical Inspection**

Airco functioning	ОК	Battery functioning	Yes
Tires wear profile	ок	Sound engine	ок
Idle position	ок	Clutch test	ок
Engine startingtime	ОК	Wiper fluid level	ок
Exhaust gass	ок	Lighting	ок
Transmission	ОК	Wiperblades	ок
Handbrake	OV		

#### Degree of wear

225/40/18/92 V LightMetal Fr.R. Continental: 7 mm Winter tyres: Continental: 7 mm Re.L. Re.R. Goodyear: 8 mm Goodyear: 8 mm

### Assistance equipment

Spare wheel	Yes Jack	Yes
Total cost ex VAT		750,00
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00





Alloy rim R L	Scratch/es1	II - Renair	and paint	(complete)
Alloy IIIII K L	scialcines),	LI - Kepali	anu panni	(complete)



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00







Rear window, Scratch(es), E - Replace

370,00









Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00





