



VOLVO V50: 1CGE535

Vinnnumber:	YV1MW84F1C2666272	Versionname:	V50 BRE DRIVe Start/Stop
First Registrationdate:	18/11/2011	Fiscalpower:	99g 115PK
Expertise Mileage:	139833	Power Kw:	84
Bodytype:	Break	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4211
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	CD
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		


Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Firestone: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Firestone: 6 mm	Re.R.	Firestone: 6 mm


Assistance equipment

Compressor	Yes
Jack	Yes

Total cost ex VAT	689,88
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	---------------



Door R R, Bump(s), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Bump(s), PDR - Knock out without painting 63,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Mirror side blinker R, Crack, E - Replace 30,00

