



**VOLVO V40: 1FMS233**

Vinnnumber:	<b>YV1MV8484E2087348</b>	Versionname:	<b>V40 D2 Base 115PK</b>
First Registrationdate:	<b>21/08/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>67985</b>	Power Kw:	<b>84</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Dark Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4406</b>
Maintenance:	<b>BINN 15675KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar removable</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of Lining	<b>Lining fabrics</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>BF Goodrich: 5 mm</b>	Fr.R.	<b>BF Goodrich: 5 mm</b>
	Re.L.	<b>BF Goodrich: 7 mm</b>	Re.R.	<b>BF Goodrich: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>708,60</b>
Bumper R, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>



Front bumper, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>
---	---------------





Door R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Roof, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Door R R, Scratch(es), Acceptable 0,00

*No pictures to display*