



## VOLVO V60: 1DQG490

Vinnumber:	<b>YV1FW88A1D1100219</b>	Versionname:	<b>V60 D4 Kinetic St/St</b>
First Registrationdate:	<b>20/07/2012</b>	Fiscalpower:	<b>163PK</b>
Expertise Mileage:	<b>110984</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Break</b>	Body color:	<b>Beige</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2223</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

## Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

## Degree of wear

	<b>235/40/18/95 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Pirelli: 4 mm</b>	Re.R.	<b>Pirelli: 4 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>
------------	------------

Total cost ex VAT	496,80
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

