



BMW 116D: 1BHU719

Vinnnumber:	WBAUH51040E776122	Versionname:	1 BER 116d 115PK
First Registrationdate:	1/06/2011	Fiscalpower:	
Expertise Mileage:	103913	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance	- 4000KM		
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/55/16/87 H Steel			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	0,00
-------------------	-------------

Rear bulkhead lining, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
---	---------------



Seat cover F L, Stain, P - Check	0,00
----------------------------------	-------------



Wheel cover R R, Scratch(es), E - Replace	30,00
---	--------------



Windscreen, Crack, E - Replace 0,00



Maintenance, Maintenance, Execute 0,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Damaged, LI - Repair and paint (complete) 259,80

