


BMW 3 BERLINE: 1KLS158

Vinnumber:	WBA3D11030F331381	Versionname:	2.0 318D (100KW) BERLINE
First Registrationdate:	28/05/2015	Fiscalpower:	
Expertise Mileage:	146327	Power Kw:	100
Bodytype:	Berline	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2231
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Front parking sensors
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/50/17/94 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Bridgestone: 9 mm	Re.R.	Bridgestone: 9 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	326,53
Door panel F R, Damaged, Smart repair	110,64



Backrest cover F L, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	

Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	

Wing R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	

Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	

Windscreen trim, Damaged, E - Replace	25,89
---------------------------------------	-------



Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	

Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	