


BMW SERIE 3 GRAN TURISMO: 1FCX205

| | | | |
|-----------------------------------|--------------------------|--------------|------------------|
| Vinnumber: | WBA3Y11050D448198 | Versionname: | 318d |
| First Registrationdate: | 25/11/2013 | Fiscalpower: | |
| Expertise Mileage: | 40362 | Power Kw: | 100 |
| Bodytype: | | Body color | Black |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | Back | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | OK |
| Maintenance | SERVICE - 1500 KM | | |
| Maintenance | NOT OK | | |
| Battery functioning | Yes | | |
| Number of doors | 5 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | | |
|--------------------------------|----------------------------------|----------------------|
| Radio CD | | Central consol F |
| GPS storage | HD | Luggage cover |
| GPS storage | | Rear parking sensors |
| Windows electric F | | |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining artificial leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 225/55/17/97 Y LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 7 mm | Fr.R. | Michelin: 7 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

Assistance equipment

| | | | |
|------------|-----------|------------|------------|
| Repair kit | No | Compressor | Yes |
|------------|-----------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 757,68 |
|-------------------|---------------|

| | |
|--|--------------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|--------------|





Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Covering interior front pillar L, Hole, E - Replace 49,35



Wing F L, Bump(s), Acceptable 0,00



Ignition key, Missing, E - Replace 0,00



Maintenance, Maintenance, Execute 0,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 307,80



Maintenance book, Missing, P - Check 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00



Tyre repair kit, Empty, E - Replace

210,53

