


**FORD S Max: 1DGE450**

Vinnumber:	<b>WF0SXXGBWSCA76398</b>	Versionname:	<b>S-MAX Econetic Trend</b>
First Registrationdate:	<b>9/05/2012</b>	Fiscalpower:	<b>St&amp;St DPF 115PK</b>
Expertise Mileage:	<b>183863</b>	Power Kw:	<b>85</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2514</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD		Panoramic roof
GPS storage		Central consol F
GPS storage	<b>HD</b>	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>215/60/16/99 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Pirelli: 4 mm</b>	Re.R.	<b>Pirelli: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	1040,16
-------------------	---------

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	115,56
---	--------



Bumper moulding R R, Scratch(es), Tu - Touch up	0,00
---	------




Bonnet, Bump(s), PDR - Knock out without painting 63,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s), PDR - Knock out without painting 82,80



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Bump(s), PDR - Knock out without painting 102,60



Windscreen, Stone chip(s), E - Replace 560,64



Bumper corner R R, Scratch(es), It - Spot repair 115,56

