


FIAT Ducato 35 MWB HR: KX5282

Vinnumber:	ZFA25000002326392	Versionname:	DUCATO 35 B/F MWB HR (EU5) 130PK
First Registrationdate:	6/01/2016	Fiscalpower:	
Expertise Mileage:	155422	Power Kw:	96
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV24
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Type of Tow bar	Tow bar fixed
Windows electric F			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining artificial leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/70/15/107 R Steel			
Winter tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	999,46
Roof, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete)	232,88



Trunk door R R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Sliding door R, Scratch(es), LI - Repair and paint (complete)

382,02



Trunk door R L, Bump(s), PDR - Knock out without painting

82,80



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)

238,76

