



AUDI A6: 1FTD606

Vinnnumber:	WAUZZZ4G6EN048506	Versionname:	A6 AVANT S-line 136PK
First Registrationdate:	16/10/2013	Fiscalpower:	
Expertise Mileage:	116329	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1426
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Seats electric F R	
GPS storage		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunction		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	NOT OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	245/45/18/100 Y LightMetal			
Summer tyres:	Fr.L.	N.D.	Fr.R.	N.D.
	Re.L.	Bridgestone: 7 mm	Re.R.	N.D.
	245/45/18/100 V LightMetal			
Winter tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	N.D.	Re.R.	Vredestein: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT

	1208,20
--	----------------

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

	95,00
--	--------------





Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Tyre R L, Not original part, P - Check 0,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Door F L, Scratch(es), LI - Repair and paint (complete) 382,02



Door F R, Repaired, P - Check 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Repaired, P - Check 0,00



Wing R R, Repaired, P - Check

0,00



Maintenance, Maintenance, Execute

0,00

