



OPEL Insignia: 1EKR970

Vinnnumber:	W0LGM5EJ6D1046092	Versionname:	INSIGNIA BER
First Registrationdate:	8/01/2013		ecoFL.Edit.150Ys DPF
Expertise Mileage:	202217		110PK
Bodytype:		Fiscalpower:	
Gearbox:	MAN 6 VIT	Power Kw:	81
Transmission:		Body color	Black
Fueltype:	Diesel	Paint type	Metalic
Battery functioning	Yes	Rims summer	Steel
Number of doors	4	Oil level	OK
Number of seats	5	Parking lot	3609
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather and alcantara
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/65/17/97 W Steel			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1723,04
Wheel cover F R, Scratch(es), E - Replace	30,00



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Interior, Dirty, Cleaning

144,00



Rocker panel inner R R, Scratch(es), LI - Repair and paint (complete)

115,56



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Bonnet, Bump(s) and scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Door F L, Scratch(es), Acceptable

0,00

No pictures to display