



OPEL Insignia: 1GAZ380

Vinnnumber:	WOLGT8ES9E1044867	Versionname:	INSIGNIA BRE ecoFLEX Cosmo 140PK
First Registrationdate:	11/12/2013	Fiscalpower:	
Expertise Mileage:	144012	Power Kw:	103
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	VS		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/55/17/97 MS LightMetal			
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	756,30
Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Bump(s), PDR - Knock out without painting	63,00



Tailgate, Scratch(es), Acceptable	0,00
--	-------------

<i>No pictures to display</i>		
Roof, Chemical polution, LI - Repair and paint (complete)		481,50
Door R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R R, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Scratch(es), LI - Repair and paint (complete)		211,80
Door F R, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		