



ALFA ROMEO Giulietta: 1FKZ217

Vinnumber:	ZAR94000007236376	Versionname:	GIULIETTA BER Distinct.Start&Stop 105PK
First Registrationdate:	1/08/2013	Fiscalpower:	
Expertise Mileage:	185113	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2713
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2142,02
Front bumper, Damaged, Le - Replace and paint	735,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Wing F R, Bump(s) and scratch(es), Le - Replace and paint 530,02



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 72,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

