



MERCEDES GLK: 1FNT477

Vinnnumber:	WDC2049841G194420	Versionname:	GLK 220 CDI BE 4M 163PK Aut.
First Registrationdate:	2/09/2013	Fiscalpower:	
Expertise Mileage:	49363	Power Kw:	120
Bodytype:	SUV	Body color:	White
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1626
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	235/60/17/102 V LightMetal			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	1053,34
-------------------	----------------

Door F R, Bump(s), PDR - Knock out without painting	63,00
---	--------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	---------------



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s), LI - Repair and paint (complete) 382,02



Bonnet, Hail damage, PDR - Hail 100,00

