



MERCEDES C: 1FMV802

Vinnnumber:	WDD2042021G184274	Versionname:	C BRE 220CDI BE Edition Avantgarde 163PK
First Registrationdate:	22/08/2013	Fiscalpower:	
Expertise Mileage:	177244	Power Kw:	120
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3605
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	190,00
-------------------	---------------

Backrest cover F L, Tear, Acceptable	0,00
--------------------------------------	-------------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------





Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

No pictures to display

Door R R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Bonnet, Bump(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Seat cover F L, Tear, Acceptable	0,00
----------------------------------	------



Door F R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Wing R L, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

