



<b>VOLKSWAGEN Polo: 1EGH373</b>	
Vinnnumber:	<b>WVWZZZ6RZDY114078</b>
First Registrationdate:	<b>23/11/2012</b>
Expertise Mileage:	<b>42197</b>
Bodytype:	<b>Hatchback</b>
Gearbox:	<b>MAN 5 VIT</b>
Transmission:	
Fueltype:	<b>Diesel</b>
Battery functioning	<b>Yes</b>
Number of doors	<b>5</b>
Number of seats	<b>5</b>
Number head rests	<b>5</b>
Rims summer	<b>Aluminium</b>
Category	<b>Passenger Car</b>
Oil level	<b>OK</b>
Versionname:	<b>POLO BER Highline DPF 105PK</b>
Fiscalpower:	<b>105PK</b>
Power Kw:	<b>77</b>
Body color	<b>Black</b>
Paint type	<b>Metalic</b>
Rims summer	<b>Aluminium</b>
Oil level	<b>OK</b>
Parking lot	<b>1528</b>

<b>Options</b>	
Radio CD	Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>
Sport seats	

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>185/60/15/88 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

<b>Assistance equipment</b>			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>

<b>Total cost ex VAT</b>	<b>1531,12</b>
<b>Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>169,44</b>



<b>Interior, Dirty, Cleaning</b>	<b>24,00</b>
----------------------------------	--------------



<b>Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>169,44</b>
--	---------------



Door R L, Scratch(es), LI - Repair and paint (complete) 254,68



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Bump(s), PDR - Knock out without painting 63,00



Seat cover F L, Hole, Smart repair 64,32



Door R R, Scratch(es), LI - Repair and paint (complete) 254,68



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 246,56



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

