



TOYOTA Auris: 1FKI057			
Vinnnumber:	SB1ZS3JE20E034509	Versionname:	AURIS TOUR.SP. HSD Lounge CVT 99PK Aut.
First Registrationdate:	25/07/2013	Fiscalpower:	
Expertise Mileage:	93063	Power Kw:	73
Bodytype:	Break	Body color	Brown
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Hybrid Petrol	Oil level	OK
Battery functioning	Yes	Parking lot	2807
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar Tow bar removable
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather and alcantara
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	876,36
Luggage space cover, Missing, E - Replace	240,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Bumper F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Bump(s), LI - Repair and paint (complete) 211,80



Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Interior, Dirty, Cleaning 24,00

