



| | | | |
|------------------------------------|--------------------------|--------------|---|
| VOLKSWAGEN Passat: 1GNR295 | | | |
| Vinnnumber: | WVWZZZ3CZEE141329 | Versionname: | PASSAT VAR Comfortline BMT 105PK |
| First Registrationdate: | 19/03/2014 | Fiscalpower: | |
| Expertise Mileage: | 147859 | Power Kw: | 77 |
| Bodytype: | Break | Body color: | Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3721 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| | | | |
|--------------------------------|------------------------------|-----------------------|----------------------|
| Options | | | |
| Radio CD | | Central consol F | |
| Windows electric F | | Luggage cover | |
| Windows electric R | | Front parking sensors | |
| Cruise Control | | Rear parking sensors | |
| Steering wheel multifunctional | | Type of Tow bar | Tow bar fixed |
| Seats F heated | | | |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

| | | | |
|-------------------------------------|-----------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

| | | | | |
|-----------------------|----------------------------------|--------------------------|-------|--------------------------|
| Degree of wear | | | | |
| | 215/55/16/97 H LightMetal | | | |
| Summer tyres: | Fr.L. | Bridgestone: 5 mm | Fr.R. | Bridgestone: 5 mm |
| | Re.L. | Kleber: 7 mm | Re.R. | Kleber: 7 mm |

| | | | |
|-----------------------------|------------|------|------------|
| Assistance equipment | | | |
| Spare wheel | Yes | Jack | Yes |

| | |
|--|---------------|
| Total cost ex VAT | 758,71 |
| Roof pillar L, Bump(s), LI - Repair and paint (complete) | 220,18 |

| | | |
|--|---|-------------|
| | Door F R, Bad repair, Acceptable | 0,00 |
|--|---|-------------|

| | | |
|--|--|---------------|
| | Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) | 318,35 |
|--|--|---------------|



| | |
|---|--------|
| Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) | 220,18 |
|---|--------|



| | |
|-----------------------------|------|
| Bonnet, Bump(s), Acceptable | 0,00 |
|-----------------------------|------|

No pictures to display

| | |
|---|------|
| Bumper R, Bump(s) and scratch(es), Acceptable | 0,00 |
|---|------|

No pictures to display