


VOLKSWAGEN Touran: 1FXG421

Vinnnumber:	WVGZZZ1TZEW044111	Versionname:	TOURAN Trendline BMT Start/Stop 105PK
First Registrationdate:	26/11/2013	Fiscalpower:	
Expertise Mileage:	141553	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4720
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/555/16/91 H LightMetal			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	583,00
-------------------	--------

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Door F R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Door panel R R, Damaged, Acceptable	0,00
-------------------------------------	------

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display