


RENAULT Megane: 1DWL113

Vinnnumber:	VF1KZ140647702733	Versionname:	MEGANE GT Energy Bose Ed.110PK
First Registrationdate:	18/09/2012	Fiscalpower:	
Expertise Mileage:	108644	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2303
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Sun Roof electric	
GPS storage	Panoramic roof	
GPS storage	SD Luggage cover	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	Tow bar removable
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-artificial leather	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/50/17/93 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

 Total cost ex VAT 624,12

 Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

 Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 301,68



Bumper R, Scratch(es), Smart repair 110,64



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Bump(s), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Damaged, Acceptable 0,00

