



VOLKSWAGEN Polo: 1DNR377			
Vinnumber:	WVWZZZ6RZDY002694	Versionname:	POLO BER Trendline 85PK
First Registrationdate:	2/07/2012	Fiscalpower:	
Expertise Mileage:	35918	Power Kw:	63
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1227
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	175/70/14/84 T Steel			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			425,50
Front bumper, Scratch(es), LI - Repair and paint (complete)			169,44



Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), E - Replace	24,00



Bonnet, Chemical polution, LI - Repair and paint (complete)	232,06
---	---------------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display