



<b>BMW 5: 1DOT698</b>			
Vinnnumber:	<b>WBAMX11030DY02372</b>	Versionname:	<b>5 TOURING 520dAS St/St 163PK Aut.</b>
First Registrationdate:	<b>10/07/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>134737</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>27208</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>			
Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Cruise Control		Sun Roof electric	
Steering wheel multifunction		Panoramic roof	
Seats F heated		Central consol F	
Type of headlighting	<b>Headlighting Xenon</b>	Luggage cover	
Type of GPS	<b>GPS big screen color</b>	Front parking sensors	
Type of Lining	<b>Lining leather</b>	Rear parking sensors	
Type of climate control	<b>Autom climate control</b>	Type of Tow bar	<b>Tow bar fixed</b>
Sport seats			

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>245/45/18/96 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

<b>Assistance equipment</b>	
Total cost ex VAT	1929,43
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	382,02
---	--------




Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door F L, Scratch(es), LI - Repair and paint (complete) 382,02



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Wing F L, Scratch(es), LI - Repair and paint (complete) 264,21

