



VOLVO V40: 1HBJ694

Vinnnumber:	YV1MV8481F2172675	Versionname:	V40 D2 Base 115PK
First Registrationdate:	11/06/2014	Fiscalpower:	
Expertise Mileage:	93791	Power Kw:	84
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1615
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Total cost ex VAT	0,00
Wing R R, Bump(s) and scratch(es), Le - Replace and paint	0,00



Headlight L, Scratch(es), 67 - Polish

55,19



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Roof, Chemical polution, Acceptable	0,00
-------------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Front bumper, Bump(s) and scratch(es), Le - Replace and paint	735,00
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Windscreen, Repaired, P - Check	0,00
---------------------------------	------

No pictures to display