



**BMW 3: 1GDV602**

Vinnumber:	<b>WBA3K11050F828535</b>	Versionname:	<b>3 TOURING 318d 136PK</b>
First Registrationdate:	<b>10/01/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>111706</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OVER 16000KM</b>	Parking lot:	<b>2408</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>
Sport seats	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>255/50/17/94 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 6 mm</b>	Fr.R.	<b>Goodyear: 6 mm</b>
	Re.L.	<b>Pirelli: 4 mm</b>	Re.R.	<b>Pirelli: 4 mm</b>

**Assistance equipment**

Runflat	<b>Yes</b>
---------	------------

Total cost ex VAT	<b>355,56</b>
-------------------	---------------

Seat cover F R, Stain, Cleaning	<b>25,00</b>
---------------------------------	--------------



Alloy rim F R, Damaged, LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Front bumper, Scratch(es), It - Spot repair 115,56



Seat cover R, Stain, Cleaning 25,00



Wing R R, Bump(s), Acceptable 0,00



Door F L, Damaged, Acceptable 0,00



Windscreen, Repaired, P - Check 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

