



**BMW X5: LA6112**

Vinnnumber:	<b>WBAK5410000H56808</b>	Versionname:	<b>X5 3.0dA xDrive30 258PK Aut.</b>
First Registrationdate:	<b>12/12/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>89188</b>	Power Kw:	<b>190</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2614</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting:	<b>Headlighting Xenon</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>255/55/18/109 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 2 mm</b>	Fr.R.	<b>Michelin: 2 mm</b>
	Re.L.	<b>Michelin: 1 mm</b>	Re.R.	<b>Michelin: 1 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>
------------	------------

Total cost ex VAT	265,00
-------------------	--------

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Interior, Dirty, Cleaning	96,00
---------------------------	-------





Door F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Door R R, Bump(s), Acceptable 0,00

*No pictures to display*

Protection plate M, Tear, E - Replace 74,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Scratch(es), Acceptable 0,00

*No pictures to display*