



BMW 1: 1ELJ938

Vinnnumber:	WBA1C91030J506623	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	14/01/2013	Fiscalpower:	
Expertise Mileage:	56257	Power Kw:	85
Bodytype:	Hatchback	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3523
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 H Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Total cost ex VAT	1133,56
Roof, Scratch(es), LI - Repair and paint (complete)	0,00



















Wheel cover F L, Scratch(es), E - Replace	30,00
---	-------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

<i>No pictures to display</i>		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wheel cover R L, Scratch(es), E - Replace		30,00
		
Luggage space cover, Missing, E - Replace		60,00
		
Bonnet, Chemical pollution, LI - Repair and paint (complete)		290,08
		
Bumper R, Scratch(es), LI - Repair and paint (complete)		211,80
		
		
		
Ignition key, Missing, E - Replace		150,00
<i>No pictures to display</i>		
Tailgate, Scratch(es), LI - Repair and paint (complete)		301,68
		
Wheel cover F R, Scratch(es), E - Replace		30,00
		
Wheel cover R R, Scratch(es), E - Replace		30,00
		
Rear window, Scratch(es), E - Replace		0,00
