



<b>BMW 3 BERLINE: 1KNH978</b>			
Vinnumber:	<b>WBA3D11040F329333</b>	Versionname:	<b>2.0 318D (100KW) BERLINE</b>
First Registrationdate:	<b>2/06/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>-1</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Berline</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:		Oil level:	<b>NOT OK</b>
Battery functioning:	<b>No</b>	Parking lot:	<b>DEP 2000 453</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>NOT OK</b>		

**Options**

Type of headlighting	<b>Headlighting Halogen</b>	Rear parking sensors	
Type of Lining	<b>Lining artificial leather</b>		

**Limited Technical Inspection**

Airco functioning	<b>NOT OK</b>	Battery functioning	<b>No</b>
Tires wear profile	<b>NOT OK</b>	Sound engine	<b>NOT OK</b>
Idle position	<b>NOT OK</b>	Clutch test	<b>NOT OK</b>
Engine startingtime	<b>NOT OK</b>	Wiper fluid level	<b>NOT OK</b>
Exhaust gass	<b>NOT OK</b>	Lighting	<b>NOT OK</b>
Transmission	<b>NOT OK</b>	Wiperblades	<b>NOT OK</b>
Handbrake	<b>NOT OK</b>		

**Degree of wear**

	<b>0/0/0/0 A LightMetal</b>			
Summer tyres:	Fr.L.	<b>N.D.</b>	Fr.R.	<b>N.D.</b>
	Re.L.	<b>N.D.</b>	Re.R.	<b>N.D.</b>

**Assistance equipment**

Total cost ex VAT	<b>0,00</b>
Bodywork, Accident, No repair	<b>0,00</b>



