



AUDI A3: TE5503			
Vinnumber:	<b>WAUZZZ8V3F1068665</b>	Versionname:	<b>A3 SED Ambition S-tr.150PK Aut.</b>
First Registrationdate:	<b>27/11/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>23871</b>	Power Kw:	<b>110</b>
Bodytype:	<b>Berline</b>	Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2507</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options			
GPS storage	<b>HD</b>	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
	<b>225/45/17/91 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 3 mm</b>	Fr.R.	<b>Pirelli: 3 mm</b>
	Re.L.	<b>Pirelli: 3 mm</b>	Re.R.	<b>Pirelli: 3 mm</b>

Assistance equipment			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>306,80</b>
Door F R, Bump(s) and scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Bumper R, Damaged, LI - Repair and paint (complete)			<b>211,80</b>



Alloy rim F.L. Scratch(es), LI - Repair and paint (complete)			<b>95,00</b>
--	--	--	--------------

Alloy rim F R, Scratch(es), Lt - Repair and paint (complete) 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00

*No pictures to display*